

SSF NOTICE

The following has been produced from a fax copy of the original; there may be some insignificant errors in spelling made difficult to read by the quality of the original facsimile.

RZECZPOSPOLITA POLSKA
GLOWNY INSPEKTORAT LOTNICTWA CYWILNEGO

REPUBLIC OF POLAND REPUBLIQUE OF POLOGNE
GENERAL INSPECTORATE INSPECTORAT GENERAL OF CIVIL AVIATION DE
L'AVIATION CIVILE

Warszawa, dn,05/06/2000 Warsaw, day/month/year

DYREKTYWA ZDATNOSCI - AIRWORTHINESS DIRECTIVE
Nr SP -0059 -2000-A

1.Przedmiot: Szybowce / gliders, model: SZD-50-3 "PUCHACZ" Product
(product name / model . applicances, numbers)

2.Number Swiadectwa Typu / Orzeczenia: GILC /GICA Type
Certificate/Approval Number (Name of Authority)

3.Dotyczy: Wykonania przegladow konsol przedniego zawieszenia
kadluba / Subject (description of the problem, identification of
part) Performance of inspections of fuselage front bracket console

4.Przyczyna wydania: Dyrektywe wydano ze wzgledu na pierwsze
informacje owykryciu
Reason for the issuance of this AD (for imported products "as in
AD" point 6)
AD issued due to first information on cracks detected in the front
bracket console, mounted on front bulkhead fuselage.

5.Dzialania korygujace: as in Mandatory Bulletin No.
Corrective action (for imported producer "as in AD" point 6)
BE-048/SZD-50-3/2000 "PUCHACZ"

6.Nazwa Wladz Lotniczych wydajacych AD: _____
Name of Aviation Authority that issued AD (for foreign "AD" give
Number and date of issue)

7.Dokumentacja zwiazana: Mandatory Bulletin No.
Ref. publications (Mandatory Bulletin)
BE-48/SZD-50-3/2000 "PUCHACZ"

Niniejsza Dyrektywa Obowiazuje z dniem: 15/06/2000
Effectivity Date of the AD: (day/month/year)

CIVIL AVIATION SAFETY AUTHORITY
14 JUN 2000
AVIATION INFORMATION SECTION

Zygmunt MAZAN
Główny Inspektor IKCSP
Chief Inspector of Civil Aircraft Inspection Board

RZECZPOSPOLITA POLSKA
GŁOWNY INSPEKTORAT LOTNICTWA CYWILNEGO

REPUBLIC OF POLAND REPUBLIQUE OF POLOGNE
GENERAL INSPECTORATE INSPECTORAT GENERAL OF CIVIL AVIATION DE
L'AVIATION CIVILE

Warszawa,
05.06.2000

day/month/year
GLC-T1-059/00/AD
Subject: Issuance of the Airworthiness Directive

NOTICE
To Whom It May Concern

This NOTICE approves and makes Mandatory the Airworthiness
Directive No SP-0059-2000-A
Dated June 5, 2000

This Airworthiness Directive concerns: All gliders of SZD-50-3
"PUCHACZ" type (aircraft, engine, propellor, equipment)

Reason for the issuance of this Airworthiness Directive: First
information on cracks detected in the front bracket console,
mounted on front bulkhead fuselage.

Enclosures:

1. Airworthiness Directive No SP-0059-2000-A
2. Mandatory Bulletin No. BE-048/SZD-50-3/2000 "PUCHACZ"

Chief Inspector of Civil Aircraft Inspection Board
Zygmunt MAZAN